

ESPECIFICACIONES TÉCNICAS / TECHNICAL CHARACTERISTICS / SPECIFICHE TECNICHE

DIBUJO / DESIGN / DISEGNO	DIANA	PISA	ROMA	MARYLE	JERTE	CELTIC	ARPA	CERAMICA
COMPOSICIÓN / COMPOSITION / COMPOSIZIONE	90% PES 10% NYLON	100% PES	100% PES	54'60% PES 45'40% CO.	54'60% PES 45'40% CO.	54'60% PES 45'40% CO.	54'60% PES 45'40% CO.	54'60% PES 45'40% CO.
ANCHO / WIDTH / LARGURA	140 cm.	140 cm.	140 cm.	140 cm.	140 cm.	140 cm.	140 cm.	140 cm.
PESO / WEIGHT / PESO (gr/m ²) +/- 5%	405 gr./m ²	420 gr./m ²	340 gr./m ²	330 gr./m ²	330 gr./m ²	330 gr./m ²	330 gr./m ²	330 gr./m ²
PESO / WEIGHT / PESO (gr/ml) +/- 5%	570 gr./ml	590 gr./ml	480 gr./ml	462 gr./ml	462 gr./ml	462 gr./ml	462 gr./ml	462 gr./ml
RESISTENCIA DE ROTURA AL RASGADO TEAR STRENGHT / RESISTENZA ALLO STRAPPO BS-3320: 1998 BS-2543: 1995	Urdimbre/Warp 200N Trama/Weft 200 N	Urdimbre/Warp 1'9 N Trama/Weft 1'5 N	Urdimbre/Warp 200N Trama/Weft 200 N	Urdimbre/Warp 3,5 mm Trama/Weft 3,8 mm	Urdimbre/Warp 3,5 mm Trama/Weft 3,8 mm	Urdimbre/Warp 3,5 mm Trama/Weft 3,8 mm	Urdimbre/Warp 3,5 mm Trama/Weft 3,8 mm	Urdimbre/Warp 3,5 mm Trama/Weft 3,8 mm
RESISTENCIA A LA ABRASIÓN / ABRASION RESISTANCE / RESISTENZA ALL'ABRASIONE CICLOS / MARTINDALE / CICLI ISO 12947-2: 1998	> 50.000	> 35.000	> 30.000	> 22.000	> 22.000	> 22.000	> 22.000	> 22.000
RESISTENCIA DE LOS COLORES A LA LUZ COLOUR FASTNESS TO LIGHT / SOLIDITÀ ALLA LUCE UNE 40187 / BS 1006-B02	4	4	4	4/5	4/5	4/5	4/5	4/5
SOLIDEZ A LA LIMPIEZA EN SECO RUBBING SOLVENTS / SOLIDITÀ AL LAVAGGIO A SECCO ISO 105D01	4	4/5	4	4/5	4/5	4/5	4/5	4/5
RESISTENCIA DE LOS COLORES AL LAVADO / RUBBING FASTNESS IN HUMID STATE / SOLIDITÀ DEI COLORI AL LAVAGGIO ISO 105D01	4	4/5	4	4/5	4/5	4/5	4/5	4/5
RESISTENCIA AL PILLING PILLING RESISTANCE / RESISTENZA AL PILLING ISO/DIS 12945-1	4	4	4	4	4	4	4	4



Lavare in lavatrice
No centrifugare
Washing machine
Lavado a máquina



Non usare candeggina
Do not use bleach
No usar lejía



Non usare asciugatrice
Do not tumble dry
No centrifugar



Transpirante
Transparent
Transpirabile



Lavare a mano max 30°C
con detergenti neutri
Hand wash, maximum 30°C
Lavar a mano, máx. 30°C



Lavabile a secco
Dry cleaning can also be used
Lavable en seco



Stirare a rovescio, max 110°C
Iron only on the rear side,
at a maximum 110°C
Planchar máx. 110°C